

MONUMENT RECORD
State of Indiana - County of Monroe

Section: 36

Township: 10 North



Range: 2 West

Corner ID: BeBl W-23

Monument Description & Remarks: 5/8" Rebar with cap, "MUNDY L.S. 880014", 3" above ground. Survey Sign 5ft above ground at pt. B

References On File: Michael Mundy survey, Thomas E. Lovell (1991), on file in Surveyor Office and Douglas R. Curry survey, Jodiet Myers Minor Subdivison (2001), on file in Recorder Instrument Number 2001020533


RECOVERY TIE DRAWING
Field Book 41 Page No. 7



- A - 5/8" Rebar with cap
- B - S 02° W 4.19' to Survey Sign on 4" Sugar Maple
- C - N 84° W 5.69' to 5/8" Rebar
- D - N 75° W 24.92' to MAG nail in 5" round post

Not To Scale
Compass Bearing Magnetic North

I, Kevin P. Enright, Monroe County Surveyor, hereby certify that this document was prepared under my direction in accordance with the provisions of section 36-2-12-11 of the Indiana Code, and the above data is given under my hand and seal this 27th day of June, 2008.



Administered by the Monroe County Surveyor Review Board

Date: 7-6-2008



Be BI W-23
06/27/2008